

# ANU ASSOCIATES

## Architect & Engineers

*M. Srihari*, B.E(civil)  
Consulting Engineer  
Cell: 97048 97049.

Date: 02.12.2023

### STRUCTURAL STABILITY CERTIFICATE

Structural Stability Certificate for building Constructed for VSM COLLEGE OF ENGINEERING in survey NO:525,526/1, Main Road,Ramachandrapuram.

I hereby certify that the Building Constructed for VSM COLLEGE OF ENGINEERING in survey no.525,526/1, Main Road,Ramachandrapuram. Has been constructed in accordance with the design specified by licensed architect and as per the approved plans by competent authority i.e Commissioner, Municipality, Ramachandrapuram vide plan B.A.No.85/2008/G1,dated24-12-2008.

The construction was done as per the standard specifications.The building is structurally sound and is suitable for running college/institutional purpose.

Signature of registered Engineer

**Er. M. SRI HARI**

BE. (Civil), F.I.V, M.I.E. MSc. (RE&V)  
Licence No : 18/SE/2019/GUDA  
Godavari Urban Development Authority  
Cell : 9704897049